PANEL MOUNTING KIT FOR IQplus 810 DESKTOP MODEL


The Panel Mounting Kit contains five screws with washers that replace the original screws holding the body to the faceplate. A template constructed from the drawing above may be used to mark the hole cut-out in the panel.

1. Unplug AC power cord before beginning.

2. Remove back of indicator by unscrewing six machine bolts holding back to faceplate.

3. Temporarily remove any cable connections from indicator terminals. Remove ground cable from cast lug on rear of indicator case.

4. Using a template made from drawing above, transfer cut-out to panel. Cut out panel and drill holes to size.

5. Hold faceplate against panel as shown and secure with five machine screws and washers provided.

6. Attach ground wire that was connected to lug on indicator body to one of five screws.

7. Re-attach cables to indicator terminals. Power up and test indicator.