

# CW-40 Over/Under Checkweigher

Base Assembly

## Part Number/Price

Part#	Description	Price
35201	Foot assembly, 10 in x 10 in and 12 in x 12 in	Consult
17449	Load cell 1040-5 k (5 lb model)	Consult
33719	Load cell 1040-10 k (10 lb model)	Consult
33722	Load cell 1040-30 k (30 lb model)	Consult
33723	Load cell 1040-50 k (50 lb model)	Consult
33724	Load cell 1040-100 k (100 lb model)	Consult
33713	Load cell 1250-200 k (200 lb model)	Consult
33715	Load cell 1250-300 k (300 lb model)	Consult
33716	Load cell 1250-500 k (500 lb model)	Consult
17480	Load cell 1250-1000 k (1000 lb model)	Consult
16836	Operating manual	Consult



CHECKWEIGHERS

**CW-40**


Indicator Assembly



**Part Number/Price**

Ref#	Part#	Description	Price
3	20063	Membrane keypad	Consult
5	20036	Gasket, enclosure	Consult
10	20037	Screw assembly, back plate	Consult
	15137	Washer, rubber	Consult
	15138	Washer, no. 8	Consult
16	19655	Power cord kit	Consult

(See Diagram CW-40-A)



CW-40-A