

# Control Unit - Wrapping, Upper Left Side

## Part Number/Price

REF #	PART #	DESCRIPTION	QTY	SYNONYM	PRICE
1	Consult	Frame, control, wrap	1	000-135-2662-74	Consult
3	Consult	Crank plate B, fixed, terminal	1	000-135-0275-05	Consult
501	171866	PWB P-1105 C-1, side wrap, rear wrap, discharge pusher, A100	1	000-149-6592-16	Consult
505	172630	Breaker, leak, Q100	1	000-086-7453-06	Consult
506	172631	Filter, noise, AC line, Z100	1	000-137-0733-09	Consult
507	72857	Fuse holder, terminal type	2	000-000-4119-04	Consult
508	72856	Fuse holder, terminal type	6	000-040-2724-07	Consult
509	47075	Fuse, glass tube, 5A, 250V, 3AG, F106, F107	2	000-033-3882-09	Consult
510	125707	Fuse, glass tube, 6A, 250V, 3AG, F100-F105	6	000-069-2407-00	Consult
511	186521	Filter, ferrite core	1	000-072-2454-03	Consult
512	171868	Electromagnetic contractor, K100, K101	2	000-092-5601-03	Consult
513	207395	Terminal block	1	000-135-0067-07	Consult
601	Consult	Harness, C10, SW (K100-A1 and K100-A2 to X306 and X102)	1	000-135-0402-39	Consult
602	Consult	Harness, C4, communication (A100 XJ5 to A300 XJ4)	1	000-133-8322-11	Consult
603	Consult	Harness, C2, heater guard (A100 XJ9 to L100)	1	000-133-8324-18	Consult
604	Consult	Harness, S4, signal (A100 XJ20 to A101 XJ7 and A100 XJ21 to A102 JX7)	1	000-133-8325-21	Consult
605	Consult	Harness, C3, power AC (U11 CN1 to F102 and F103)	1	000-133-8340-27	Consult
606	211517	Harness, C17, signal (A100 XJ8 to B100, B101, B102, X61, X100, X101, and X102)	1	100-003-2493-00	Consult
607	Consult	Harness, C4, noise filter (Q100 to Z100)	1	000-134-8924-29	Consult
609	Consult	Harness, C4, seal heater (F106 to K200-1 and K201-1)	1	000-134-8933-22	Consult
610	Consult	Harness, C6, seal heater (F107 to X213 (E201) and X212 (E200) to K200-2 and K201-2)	1	000-134-8934-44	Consult
612	Consult	Harness, S4, power AC (K101-4 to F104 and K101-2 to F105)	1	000-134-8990-16	Consult
613	Consult	Harness, C3, power AC (F104 and F105 to U100 CN1)	1	000-134-8992-13	Consult
614	Consult	Harness, C3, power AC (F104 and F105 to U101 CN1)	1	000-135-0063-11	Consult
615	Consult	Harness, C8, sensor (A100 XJ28 to B106, B106T, B107, and B107T and A100 XJ18 to X107)	1	000-135-2532-37	Consult
617	Consult	Harness, C4, power AC (K100-2 to A100-L and K100-4 to A100-N)	1	000-134-8936-32	Consult
618	Consult	Harness, C4, power AC (K101-4 to A300-L and K101-6 to A300-N)	1	000-134-8938-11	Consult
619	Consult	Harness, C4, power AC (K100-6 to A200-L and K101-2 to A200-N)	1	000-134-8937-18	Consult
620	Consult	Harness, S16, power AC (F106 to K100-5 and F107 to K100-3)	1	000-134-8928-23	Consult
621	Consult	Harness, C13, power AC (Z100 to F100, F101, and X109)	1	000-139-9346-08	Consult
622	Consult	Harness, C3, power AC (U10 CN1 to F100 and F101)	1	000-134-8977-26	Consult
623	Consult	Harness, C4, power AC (A100 XJ12 to X13, X50, and X108)	1	000-134-8980-46	Consult
624	Consult	Harness, C4, power AC (220V input terminal to Q100)	1	100-001-5774-01	Consult
<b>WM-Ai-P</b>					
999	178268	Relay, G7J-4A-B 220/240VAC, K110	1	000-144-9605-05	Consult

# Ishida WM-Ai

Control Unit - Wrapping, Upper Left Side

