

# Wrapper Main Body Unit

See Uni-7 RP page 211 for Controller Parts List

## Part Number/Price

REF #	PART #	DESCRIPTION	QTY	SYNONYM	PRICE
1	Consult	Frame side R	1	135-4654-53	Consult
2	Consult	Frame side L	1	135-4655-48	Consult
3	Consult	Cover inside tray	1	135-4670-26	Consult
4	Consult	Guide under tray L	1	137-0621-14	Consult
5	Consult	Guide under tray R	1	137-0624-24	Consult
6	Consult	Cover wiring L	1	137-0559-16	Consult
7	Consult	Guide rail upper unit	1	137-0570-09	Consult
8	Consult	Guide rail upper unit	1	137-0571-11	Consult
9	Consult	Bracket solenoid side	2	136-3945-23	Consult
10	179667	Timing belt S3M polished	1	041-2526-03	Consult
11	125714	Motor assy stepping, film feed (M2)	1	137-0538-18	Consult
12	Consult	Bracket sensor	1	142-6111-07	Consult
	Consult	Bracket sensor (from s/n 100556002) required for 507F and 507R	1	100-048-0070-00	Consult
13	Consult	Cover sensor	1	142-6110-03	Consult
	Consult	Cover sensor (from s/n 100556002) required for 507F and 507R	1	100-048-0071-00	Consult
14	Consult	Bracket, adjustable, sensor (from s/n 100556002) required for 507F and 507R	1	100-048-0069-00	Consult
15	Consult	Harness S1, jumper (P-1004 A1 XJ8)	1	137-0659-06	Consult
51	Consult	Stay main body F	1	135-4647-48	Consult
52	Consult	Stay main body R	1	135-4648-23	Consult
53	174431	Foot adjustment	4	001-4902-01	Consult
54	Consult	Stay guide tray	1	132-6279-28	Consult
55	Consult	Stay front	1	135-4657-27	Consult
56	Consult	Stay rear	1	135-4658-21	Consult
57	Consult	Guide positioning upper unit	1	135-4659-15	Consult
59	Consult	Guide tray	1	137-8077-35	Consult
60	Consult	Guide tray	1	137-8078-39	Consult
61	Consult	Cover inside upper	1	135-4672-14	Consult
62	185555	Cover inside	1	132-6283-60	Consult
63	185556	Cover inside	1	132-6284-63	Consult
64	Consult	Cover protect F	1	137-0578-08	Consult
65	Consult	Cover protect R	1	137-0579-01	Consult
66	Consult	Guide link feed	1	137-0569-04	Consult
67	Consult	Stay weigh	1	135-4645-04	Consult
68	Consult	Stay weigh	1	135-4646-08	Consult
69	Consult	Bracket motor stepping	1	135-4860-09	Consult
70	203918	Timing pulley S3M C	1	138-5877-07	Consult
71	Consult	Bracket solenoid center	2	136-3944-11	Consult
72	157782	Spring coil compressive	4	064-0192-06	Consult
73	125701	Solenoid assy clamp (L1, L2, L3, L4)	4	073-7078-01	Consult
74	Consult	Link solenoid	4	135-2581-21	Consult
75	Consult	Collar	2	017-6857-07	Consult
76	Consult	Bracket sensor	2	135-2566-15	Consult
77	Consult	Actuator sensor	2	135-2567-55	Consult
78	Consult	Collar	2	017-6858-01	Consult
79	Consult	Bracket switch	1	137-8232-09	Consult
501	72899	Switch push emergency (S2)	1	064-9296-02	Consult
502	172632	Thermistor assy heater right, fan temperature (R141), 3.3K ohm	1	111-8426-11	Consult
503	125711	Photo interrupter, sensor, transmitter, high volume, right (B3)	1	112-9768-07	Consult
504	125712	Photo interrupter, sensor, receiver, high volume, left (B6)	1	112-9769-01	Consult
505	104239	Photo interrupter trans, lift home and film over, white conn. (B1, B9, B10)	3	070-5204-14	Consult
506	Consult	Accessory band marking	1	135-0340-04	Consult
507†	154221	Sensor assy, film detect sensor, black (use for both front & rear) (B14, B15)	2	141-6232-07	Consult
507F†	211722	Sensor assy, film detect sensor, front, blue (B14) from s/n 100556002	1	100-047-3317-00	Consult
507R†	211723	Sensor assy, film detect sensor, rear, blue (B15) from s/n 100556002	1	100-047-3318-00	Consult
508*	209590	Harness C4 sensor (P-1004 A1 XJ10 to B14, B15, and B16)	1	143-0922-06	Consult
509	Consult	Accessory band marking tie	1	142-6393-01	Consult
510	Consult	Accessory band marking tie	1	142-6394-04	Consult

† Install PN 211722 (blue) and PN 211723 (blue) as a set. Do not mix PN 154221 (black) with either PN 211722 (blue) or PN 211723 (blue).

\*See the [WM-Nano Wiring Diagrams on page 161](#) and [page 162](#) for harness details; 1-15, 2-508, 2-602 and 2-603

ISHIDA WM-NANO

# Wrapper Main Body Unit

See Uni-7 RP page 211 for Controller Parts List

## Part Number/Price

REF #	PART #	DESCRIPTION	QTY	SYNONYM	PRICE
602*	Consult	Harness C8 solenoid (P-1004 A1 XJ21, XJ22, and XJ35 to L1, L2, L3, L4, L5, L6, and L7)	1	132-2006-23	Consult
603*	181064	Harness C9 sensor (P-1004 A1 XJ7 and XJ11 to B1, B3, B6, B9, B10, X3P, and X4P)	1	132-2007-54	Consult
—	41732	Screw, cover, SST, M4x6		00-0237-06	Consult

\*See the [WM-Nano Wiring Diagrams on page 161](#) and [page 162](#) for harness details; 2-508, 2-602 and 2-603

# Ishida WM-Nano

Wrapper Main Body Unit

